



F I G. 4



F I G. 5







	FLUID LEAK		BOOSTER	NODMAL
	SMALL	LARGE	FAILURE	NORMAL
F≒F0 (F0' ≦F <f1)<br="">PMO ≧Pth1</f1>	0	×	×	0
F≒F2 (F2 <f) PM2 ≧Pth2</f) 	×	×	0	0
BOTTOMING CONDITION DETECTED	0	0	×	×
$\frac{\text{dPM}}{\text{dt}} < \beta \ (\beta < 0)$	0	×	×	×

O: SATISFIED WITH THE LEFT CONDITION

×: NOT SATISFIED WITH THE LEFT CONDITION

F I G. 7





F I G. 9








FIG. 10








SERVO FUNCTION FAILURE IN THE BRAKE OPERATION



(a) CHANGE OF THE MASTER PRESSURE



(b) CHANGE OF THE OPERATING POWER

FIG. 14

